

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b> 04D0465341	<b>(X3) Date Survey Completed</b> 04/30/2026
<b>Name of Provider or Supplier</b> Family Clinic Of Ashley County Pa	<b>Street Address, City, State</b> 909 Unity Road, Crossett, AR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6120</b>	<p><b>TECHNICAL SUPERVISOR RESPONSIBILITIES</b> CFR(s): 493.1451(b)(7)(8)</p> <p>(b)(7) Identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on the form CMS 209, laboratory policy and procedure, personnel records, lack of documentation, and interview, the laboratory failed to document competency of the General Supervisor (GS) on an annual basis. Findings follow: A) Review of the CMS 209 form revealed that the one of one GS (listed on the form CMS 209) was employed by the laboratory since 2021. B) Review of competency assessment records revealed that one of one GS (listed on the CMS 209 form) had no competency evaluations in 2025 and 2026. C) Upon request, the laboratory was unable to provide any competency assessments for the position of GS for 2025 and 2026. D) In an interview, at 12:33 pm on 3/29/2026, the Laboratory Directory confirmed no competency assessments had been performed for the GS listed on the CMS 209 form for 2025 and 2026.</p>