

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 04D0666802	(X3) Date Survey Completed 08/07/2025
Name of Provider or Supplier Unity Health Searcy Medical Center	Street Address, City, State 2900 Hawkins Drive, Searcy, AR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6032	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1407(e)(14)</p> <p>(e)(14) Specify, in writing, the responsibilities and duties of each consultant and each person, engaged in the performance of the preanalytic, analytic, and postanalytic phases of testing, that identifies which examinations and procedures each individual is authorized to perform, whether supervision is required for specimen processing, test performance or results reporting, and whether consultant or director review is required prior to reporting patient test results.</p> <p>This STANDARD is not met as evidenced by: Based on review of personnel files for all testing personnel listed on the CMS-209 form, lack of documentation, and interviews with laboratory staff, determined the laboratory director failed to authorize two of six testing personnel to perform testing without direct supervision. Survey findings include: A) During a review of personnel files for all testing personnel (TP), TP- 1 and TP- 2 (as listed on the form CMS-209) failed to have written authorization from the laboratory director, to perform moderate complexity for the new Sysmex XN-530 hematology instrument without direct supervision. B) In an interview on 8/7/2025 at 2:20 pm, the TP-1 on the CMS 209 form confirmed the lack of written authorization for two TP on form CMS 209.</p>