

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  05D0560960	<b>(X3) Date Survey Completed</b>  08/27/2024
<b>Name of Provider or Supplier</b>  Ken S Honbo Md / Arash Nourparvar Md	<b>Street Address, City, State</b>  16311 Ventura Blvd, Ste 880, Encino, CA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6046</b>	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on lack of documentation for competency assessments for the years 2022, 2023, and 2024 and interviews with the technical consultant and testing personnel; it was determined that the technical consultant failed to perform and document the performance evaluation for one of the testing personnel and assuring that they maintained their competency to perform test procedures promptly, accurately, and proficiently.</p>