

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  05D0699992	<b>(X3) Date Survey Completed</b>  12/19/2018
<b>Name of Provider or Supplier</b>  William J Wickwire, Md Inc	<b>Street Address, City, State</b>  275 Victoria St Ste 2h, Costa Mesa, CA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D3007</b>	<p><b>FACILITIES</b> CFR(s): 493.1101(b)</p> <p>The laboratory must have appropriate and sufficient equipment, instruments, reagents, materials, and supplies for the type and volume of testing it performs.</p> <p>This STANDARD is not met as evidenced by: Based on observation of multiple Flammable reagents for processing and staining histopathology slides during Mohs procedures, the lack of a Flammables cabinet, and interview with a laboratory person, the laboratory failed to have an appropriate storage cabinet for Flammable materials. Findings include: a. The laboratory stored multiple containers of flammable reagents in the cabinet under the sink: Flammable reagent Quantity ----- Xylene substitute 2 containers, 1 Gallon each 100% Reagent Alcohol 1 x 1 Gallon Methanol 1 x 1 Gallon Isopropyl Alcohol 1 x 1 Gallon b. A laboratory person affirmed (12/19/18) the aforementioned flammable chemicals were routinely stored under the sink; and thus, the laboratory's failure to have the appropriate Flammables cabinet for storage. c. The volume of improperly stored Flammable chemicals totaled 5 Gallons. .</p>
<b>D6084</b>	<p><b>LABORATORY DIRECTOR RESPONSIBILITIES</b> CFR(s): 493.1445(e)(2)</p> <p>The laboratory director must ensure that the physical plant and environmental conditions provide a safe environment in which employees are protected from physical, chemical, and biological hazards.</p> <p>This STANDARD is not met as evidenced by: Based on the deficiency cited (D3007), the Laboratory Director is herein cited for deficient practice in ensuring a safe environment in which employees are protected</p>

from flammable chemical hazards. Findings include: a. The Laboratory Director required flammable chemicals to be stored onsite, but failed to ensure an appropriate storage cabinet for Flammable materials was obtained. b. See D3007.