

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 05D2197767	(X3) Date Survey Completed 02/05/2026
Name of Provider or Supplier Sollis Health La, Pc	Street Address, City, State 155 N San Vincente Blvd 1st Fl, Beverly Hills, CA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2087	<p>ROUTINE CHEMISTRY CFR(s): 493.841(a)</p> <p>(a) Failure to attain a score of at least 80 percent of acceptable responses for each analyte in each testing event is unsatisfactory analyte performance for the testing event.</p> <p>This STANDARD is not met as evidenced by: Based on the surveyor's review of the American Proficiency Institute (API) proficiency testing (PT) records and interviews with the technical consultant (TC) and laboratory supervisor (LS), it was determined that the laboratory failed to attain at least 80 percent of the acceptable score in Routine Chemistry for the Creatine Kinase analyte in the second event of 2025 (Q2-2025). The findings include: 1. The surveyor reviewed the PT records wherein API reported an unsatisfactory score of 20% for the Creatine Kinase analyte in Routine Chemistry for the Q2-2025 event. The report is as followed: Sample Reported Expected CH-06 18 17 - 27 CH-07 *193 211 - 318 CH-08 95 92 - 139 CH-09 *150 159 - 239 CH-10 259 278 - 418 Legend: * = unsatisfactory score 2. The TC and TP affirmed by interviews on February 5, 2026, at approximately 12:35 p.m. that the laboratory obtained the unsatisfactory PT scores for Creatine Kinase analyte as mentioned in statement #1. 3. The accuracy and reliability of patient test reported cannot be determined. 4. According to the laboratory's testing declaration form (Lab-144) submitted on the day of the survey, the laboratory performed approximately 50 patient test samples annually for Creatine Kinase analyte during the time the laboratory received unsatisfactory proficiency testing scores. .</p>
D6016	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1407(e)(4)(i)</p> <p>(e)(4)(i) The proficiency testing samples are tested as required under Subpart H of this part;</p>

This STANDARD is not met as evidenced by:

Based on the surveyor's review of the laboratory's proficiency testing documentation and interviews with the technical consultant and laboratory supervisor on February 5, 2026, this deficiency is herein cited for the laboratory director due to failure to ensure that proficiency testing samples were tested as required under Subpart H of this part. See D2087.