

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 06D1100435	(X3) Date Survey Completed 07/12/2024
Name of Provider or Supplier Quicksilver Scientific Inc	Street Address, City, State 1960 Cherry Street, Louisville, CO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6127	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9)</p> <p>The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least semiannually during the first year the individual tests patient specimens.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the laboratory's personnel records, and an interview with the technical supervisor (TS), and general supervisor #2 (GS #2), the laboratory failed to evaluate and document the competency of five out of five testing personnel (TP) listed on the CMS-209 form semiannually during their first year of employment since the laboratory's last survey was conducted on November 24, 2021. The laboratory performs approximately 9,100 toxicology tests annually. Findings include: 1. A review of the laboratory's personnel files revealed there was no semiannual evaluation of competency documented for five out five TP listed on the CMS-209 form during their first year of employment. 2. An interview with the TS, at approximately 11:30 AM on July 12, 2024, confirmed that the laboratory failed to evaluate and document the competency of five out of five TP listed on the CMS-209 form semiannually during their first year of employment. 3. An interview with GS #2, at approximately 11:32 AM on July 12, 2024, confirmed that the laboratory failed to evaluate and document the competency of five out of five TP listed on the CMS-209 form semiannually during their first year of employment.</p>