

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 06D2218127	(X3) Date Survey Completed 03/21/2025
Name of Provider or Supplier Vascular Labs Of The Rockies Asc, Llc	Street Address, City, State 4105 E Florida Avenue Ste 100, Denver, CO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The following deficiencies are a result of a desk review of proficiency testing scores obtained from the national database and verified with the laboratory manager. The facility was found to be out of compliance with the conditions of the CLIA program. The following condition level deficiencies were found to be out of compliance: 42 C.F.R. 493.803 Condition: Successful Participation [proficiency testing];
D2016	<p>SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c)</p> <p>(a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history.</p> <p>This CONDITION is not met as evidenced by: Based on a routine desk review of the CMS-155 report for proficiency testing performance and phone communication with the laboratory manager, the laboratory failed to achieve satisfactory performance scores for the Wisconsin State Laboratory</p>

of Hygiene proficiency testing for Hemoglobin (non-waived) for two out of three PT events, (event 1 in 2024 and event 3 in 2024). See D2130.

D2130

HEMATOLOGY
CFR(s): 493.851(f)

(f) Failure to achieve satisfactory performance for the same analyte in two consecutive events or two out of three consecutive testing events is unsuccessful performance.

This STANDARD is not met as evidenced by:
Based on a routine desk review of the CMS-155 report for Proficiency Testing (PT) performance, and a phone call with the laboratory's manager, the laboratory failed to achieve a satisfactory score for two out of three Wisconsin State Laboratory of Hygiene (WSLH) PT events for the analyte: Hemoglobin (non-waived), for event 1 and event 3 in 2024. Findings include: 1. A review of the CMS-155 report for PT performance on February 7, 2025, at 9:33 AM, revealed the WSLH PT results for the analyte: Hemoglobin (non-waived), was 60% for event 1, and 0% for event 3 in 2024. 2. A phone call with the laboratory manager on March 21, 2025, at approximately 9:40 AM, confirmed that the laboratory failed to achieve satisfactory PT scores for two out of three events for the following analyte: Hemoglobin (non-waived), for event 1 and event 3 in 2024.