

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D0285519	<b>(X3) Date Survey Completed</b>  01/28/2020
<b>Name of Provider or Supplier</b>  Bss International Inc	<b>Street Address, City, State</b>  7777 N University Dr Ste 102, Tamarac, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	A recertification survey conducted on 01/29/2020 found that BSS International Inc clinical laboratory was not in compliance with 42 CFR Part 493, Requirements for Laboratories.
<b>D2153</b>	<p><b>ABO GROUP AND D(RHO) TYPING</b> CFR(s): 493.859(a)</p> <p>Failure to attain a score of at least 100 percent of acceptable responses for each analyte or test in each testing event is unsatisfactory analyte performance for the testing event.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview with laboratory personnel, the laboratory failed to get 100% for 1 out of 6 testing events reviewed during 2018-2019 for D(Rho) typing. Findings include: Review of the American Proficiency Institute (API) proficiency testing (PT) records revealed that the laboratory received 80 % for Rhesus (Rh) testing for the 3rd event of 2018. During an interview on 01/29/2020 at 2:30 pm, the testing personnel (TP) A confirmed that they received 80 % testing score for the event of above reference.</p>