

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D0973837	(X3) Date Survey Completed 03/25/2026
Name of Provider or Supplier Surgical Pathology Laboratories Pa-Mlu 5	Street Address, City, State 8455 66th St N, Pinellas Park, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at Surgical Pathology Laboratories PA-MLU5 on 03/25/2026. The laboratory is not in compliance with 42 CFR Part 493 CLIA requirements. A standard deficiency was cited as follows:
D3011	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: Based on observations, record review, and interview, the laboratory failed to ensure protection from chemical hazards for two of two years 03/2024 through 03/2026. Findings included: 1. A tour of the mobile unit was performed 03/26/2026 at 10:10 a. m. An autostainer was observed with no fume hood present. 2. The safety data sheet for Sub-X Xylene Substitute with a revision date of 01/16/2018 was reviewed. Exposure controls or personal protection included Good ventilation of the work station and "wear respiratory protection". 3. The Laboratory Supervisor was interviewed on 03/26/2026 at 10:10 a.m. They confirmed the lab did not use a fume hood when utilizing this reagent.</p>