

| | | |
|--|---|---|
| Statement of Deficiencies | (X1) Provider/Supplier/CLIA Identification Number 10D1044073 | (X3) Date Survey Completed 05/06/2022 |
| Name of Provider or Supplier United Laboratory Services Corp | Street Address, City, State 7095 Sw 47th St Bldg B, Miami, FL | |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. | | |

| (X4) ID Prefix Tag | Summary Statement of Deficiencies |
|---------------------------|---|
| D0000 | A complaint survey for 2022004782, was conducted on 5/5/2022-5/6/2022 at United Laboratory Services Corp. The laboratory was not in compliance with 42 CFR Part 493, Requirements for Laboratories. |
| D5813 | <p>TEST REPORT CFR(s): 493.1291(g)</p> <p>The laboratory must immediately alert the individual or entity requesting the test and, if applicable, the individual responsible for using the test results when any test result indicates an imminently life-threatening condition, or panic or alert values.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview, the laboratory failed to report critical Prothrombin Time (PT) and International normalized ratio (INR) results to the medical provider for patient # 1 on 3/25/2022 and 3/29/2022. Findings included: A review of PT and INR testing reports revealed patient #1 test results were critical values for PT- 34.1 and INR -2.67 on 3/25/2022. Patient #1 test results were critical values for PT-27.3 and INR-2.13 on 3/29/2022. A review of March 2022 PT and INR fax reports revealed that critical PT and INR results for patient #1 were not faxed to their doctor's office on 3/25/2022 and 3/29/2022. During an interview on 5/6/2022 at 2:14 PM, the owner confirmed the staff failed to fax critical PT and INR results for patient #1 on 3/25/2022 and 3/29/2022 to their doctor.</p> |