

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1099045	(X3) Date Survey Completed 12/16/2020
Name of Provider or Supplier Dermatology Southeast - Sunbeam	Street Address, City, State 4727 Sunbeam Rd Ste 102, Jacksonville, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	At the time of the announced, on-site recertification survey, Southside Dermatology was found to NOT be in compliance with the CLIA laboratory requirements of 42 CFR 493. .
D5217	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on record review and staff interview, the laboratory failed to verify the accuracy of KOH (potassium hydroxide) testing at least twice a year for 2 of 2 (2019 - 2020) years reviewed. Findings Included: Review of peer review records showed no documentation of twice annual verification of KOH testing. Interview with the Laboratory Director on 12/16/20 at 10:00am confirmed that no peer review was performed for KOH during the 2 year period (2019-2020) when patient testing was performed.</p>