

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D2096689	(X3) Date Survey Completed 06/30/2025
Name of Provider or Supplier Apls Services Llc D/B/A Clear Diagnostics	Street Address, City, State 708 E Tarpon Ave, Tarpon Springs, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at APLS Services LLC dba Clear Diagnostics on 06/30/2025. The laboratory is not in compliance with 42 CFR Part 493, Requirements for Laboratories. The following is a description of the standard level deficiency:
D6120	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(7)(8)</p> <p>(b)(7) Identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview, the Technical Supervisor failed to perform an initial and 6 month competency assessment for one testing person (TP #A) of seven TP (#A - #G). Findings included: The owner stated during an interview on 06/30/2025 at 10:30 a.m. that TP #A's date of hired was 08/2023. Competency assessments for TP #A were reviewed. An initial and 6 month competency were not present. Interview with the owner at 11:15 a.m. on 06/30/2025 confirmed the initial and 6 month competencies were not present.</p>