

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D2176775	<b>(X3) Date Survey Completed</b>  12/16/2025
<b>Name of Provider or Supplier</b>  Conceptions Fertility Laboratories Llc	<b>Street Address, City, State</b>  2750 Sw 145th Ave Suite 103, Miramar, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	An announced CLIA recertification survey was conducted at CONCEPTIONS FERTILITY LABORATORIES LLC from 12/10/2025 to 12/16/2025. The laboratory was surveyed under 42 CFR Part 493 CLIA requirements. Standard deficiency cited as follows:
<b>D5805</b>	<p>TEST REPORT CFR(s): 493.1291(c)</p> <p>(c) The test report must indicate the following: (c)(1) For positive patient identification, either the patient's name and identification number, or a unique patient identifier and identification number. (c)(2) The name and address of the laboratory location where the test was performed. (c)(3) The test report date. (c)(4) The test performed. (c)(5) Specimen source, when appropriate. (c)(6) The test result and, if applicable, the units of measurement or interpretation, or both. (c)(7) Any information regarding the condition and disposition of specimens that do not meet the laboratory's criteria for acceptability.</p> <p>This STANDARD is not met as evidenced by: Based on review of patient reports for semen analysis and staff interview, the laboratory failed to ensure that the patient reports had the name of the Laboratory at least since 05/07/2024. Findings included: 1-Review of 4 final patient reports: P#1 (date 05/07/2024), P#2 (date 11/05/2024), P#3 (date 03/05/2025) and P#4 (date 12/09/2025); revealed that the reports failed to list the name of the laboratory that did the semen analysis as it is listed in the Certificate of Compliance. 2-During an interview on 12/10/2025 at 01:45 PM, Testing Personnel #1 confirmed that the patient reports failed to show the name of the laboratory that performed the semen analysis and on 12/15/2025 the Technical Supervisor confirmed that the reports did not have the correct name of the laboratory.</p>