

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D2326388	(X3) Date Survey Completed 12/03/2025
Name of Provider or Supplier Estero Dermatology & Skin Surgery Center, Llc	Street Address, City, State 10200 Arcos Avenue Suite 201, Estero, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA initial survey was conducted at Estero Dermatology & Skin Surgery Center, LLC on 12/03/2025. The laboratory was surveyed under 42 CFR Part 493 CLIA requirements. A Standard deficiency was cited and is as follows:
D3011	FACILITIES CFR(s): 493.1101(d) Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials. This STANDARD is not met as evidenced by: Based on observation, interview, and record review, the laboratory failed to ensure protection from chemical hazards from 7/21/2025 through 12/03/2025. Findings 1. During a tour of the laboratory on 12/3/2025 at 11:45 a.m., no fume hood was observed in the laboratory. 100% Reagent Alcohol for Histology testing was in use and stored in the safety cabinet. Hazard labeling on the 100% Alcohol stated "Do not breathe dust/fumes/gas/mist/vapors/spray". 2. The contracted Laboratory Consultant confirmed on 12/03/2025 at 1:00 p.m. the laboratory did not have a process in place to ensure air quality safety from chemical hazards and did not have a fume hood in place.