

| | | |
|--|--|---|
| Statement of Deficiencies | (X1) Provider/Supplier/CLIA Identification Number 13D1105419 | (X3) Date Survey Completed 01/14/2026 |
| Name of Provider or Supplier Southern Idaho Pain Institute Pc | Street Address, City, State 120 Rose St N, Twin Falls, ID | |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. | | |

| (X4) ID Prefix Tag | Summary Statement of Deficiencies |
|---------------------------|--|
| D5413 | <p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(b)</p> <p>(b) The laboratory must define criteria for those conditions that are essential for proper storage of reagents and specimens, accurate and reliable test system operation, and test result reporting. The criteria must be consistent with the manufacturer's instructions, if provided. These conditions must be monitored and documented and, if applicable, include the following: (b)(1) Water quality. (b)(2) Temperature. (b)(3) Humidity. (b)(4) Protection of equipment and instruments from fluctuations and interruptions in electrical current that adversely affect patient test results and test reports.</p> <p>This STANDARD is not met as evidenced by: Based on a lack of laboratory temperature and humidity logs and an interview with the technical supervisor (TS) on 1/14/2026, the laboratory failed to monitor the testing temperature and humidity since the previous inspection on 12/4/2023. The findings include: 1. A lack of laboratory temperature and humidity logs identified the laboratory failed to monitor testing temperature and humidity per the Shimadzu LCMS /MS manufacturer requirements. 2. An interview with the TS on 1/14/2026 at 2:10 pm confirmed that the laboratory failed to monitor temperatures and humidity since the last inspection on 12/4/2023. 3. The laboratory reports performing 67,200 toxicology tests annually.</p> |