

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  13D2000081	<b>(X3) Date Survey Completed</b>  10/23/2018
<b>Name of Provider or Supplier</b>  Idaho Skin Institute Of Chubbuck	<b>Street Address, City, State</b>  147 W Chubbuck Rd, Chubbuck, ID	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6120</b>	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on a record review of personnel competency assessments and an interview with the laboratory lead, the laboratory director who is the technical supervisor failed to evaluate the competency of 3 out of 3 testing personnel who perform microscopic examinations for fungal presence using potassium hydroxide (KOH). This is a repeat deficiency from the last survey on September 9, 2016. Findings: 1. A review of personnel documents revealed the technical supervisor failed to evaluate the competency for 3 out of 3 mid-level practitioners who perform KOH examinations since the last survey. 2. An interview on October 23, 2018 at 9:150 AM, with the laboratory lead, confirmed the technical supervisor failed to assess and document the competency for the 3 mid-level practitioners.</p>