

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 15D0647560	(X3) Date Survey Completed 04/29/2026
Name of Provider or Supplier Twin Rivers Medical Laboratory, Inc	Street Address, City, State 902 W Broadway, Logansport, IN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A Proficiency Testing (PT) Desk Review (DR) was completed on 4-29-2026. The following condition level deficiencies were found to be out of compliance: D2016- 42 C.F.R. 493.803 Condition: Successful participation (proficiency testing).
D2016	<p>SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c)</p> <p>(a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history.</p> <p>This CONDITION is not met as evidenced by: Based on the PTDR of the Certification and Survey Provider Enhanced Reporting (CASPER) 0155D report and interview with the laboratory owner, the laboratory failed to successfully participate in the American Proficiency Institute (API) PT event 3 of 2025 and event 1 of 2026 in the Subspecialty of Routine Chemistry for the analyte Chloride resulting in an initial unsuccessful participation. Refer to D2096.</p>

D2096

ROUTINE CHEMISTRY

CFR(s): 493.841(f)

(f) Failure to achieve satisfactory performance for the same analyte or test in two consecutive testing events or two out of three consecutive testing events is unsuccessful performance.

This STANDARD is not met as evidenced by:

Based on PTDR of the CASPER 0155D report and interview with Staff Person (SP) -01 (Owner) on 4-29-2026 at 10:07 am, the laboratory failed to achieve satisfactory performance for 2 consecutive API PT testing events (event 3 2025 and event 1 2026) in the Subspecialty of Routine Chemistry for the analyte Chloride. Findings include:

1. Review of the CASPER report 0155D indicated the following unsuccessful scores for the analyte Chloride in the Subspecialty Routine Chemistry a. Event 3- 2025=60% b. Event 1- 2026=40%
2. In an interview with SP-01 (Owner) on 4-29-2026 at 10:07 am SP-01 confirmed the API test scores for the analyte Chloride for event 3-2025 and event 1-2026. SP-01 could not provide the API evaluation for the two events.