

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 16D0385165	(X3) Date Survey Completed 10/09/2018
Name of Provider or Supplier Unitypoint Clinic	Street Address, City, State 319 Sergeant Square Drive, Sergeant Bluff, IA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6054	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on review of personnel records and confirmed by laboratory personnel identifier #3 (refer to the Laboratory Personnel Report) at approximately 1:30 pm on 10/09/2018, the technical consultant failed to assess and document the competency of individuals performing moderate complexity testing at least annually for two out of two testing personnel (laboratory personnel identifiers #3 and #4) in 2016 and 2017.</p>