

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 17D0448967	(X3) Date Survey Completed 05/22/2025
Name of Provider or Supplier Sunflower Medical Group Pa	Street Address, City, State 5675 Roe Blvd, Ste 100, Roeland Park, KS	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: An on-site revisit was conducted 5/22/25. Based on the review of the CMS 209 personnel form and interview with TC #1, the TC failed to evaluate competency for one of five moderate complexity testing personnel (TP). Findings: 1. Review of the CMS 209 personnel form for the validation survey conducted 12/3/24 revealed five moderate complexity TP. 2. Interview with TC #1 revealed that TP #4 and TP #5 were no longer employed at this laboratory. 3. The surveyor requested competency documentation for TP #2 and TP #3. No documentation for TP #2 competency was provided at the time of survey. 4. Interview with TC #1 on 5/22/25 at 10:45 a.m. confirmed, the TC failed to evaluate competency for one of five moderate complexity TP..</p>