

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 17D0453273	(X3) Date Survey Completed 12/01/2020
Name of Provider or Supplier Hamilton County Hospital	Street Address, City, State 700 Huser Street, Syracuse, KS	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6120	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on a review of competency assessment records, and interview, the technical supervisor failed to evaluate the competency for one of two testing personnel (TP). Findings: 1. No competency assessment records (including both 6 month and annual) for TP #1 were made available at the time of survey. 2. Interview with General Supervisor on December 1, 2020 at 3:15 p.m. confirmed, the technical supervisor failed to evaluate the competency for one of two testing personnel (TP).</p>