

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  17D0936738	<b>(X3) Date Survey Completed</b>  08/26/2020
<b>Name of Provider or Supplier</b>  Comprehensive Health Of Planned Parenthood	<b>Street Address, City, State</b>  2312 S Tucker Terrace, Pittsburg, KS	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5221</b>	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(d)</p> <p>All proficiency testing evaluation and verification activities must be documented.</p> <p>This STANDARD is not met as evidenced by: Based on review of the laboratory's American College of Physicians (ACP) proficiency testing (PT) documentation and interview with testing personnel #2, the laboratory failed to document all proficiency testing evaluation and verification activities for five of the eight testing samples for Testosterone in 2019 and 2020.. Findings Include: 1. Review of the laboratory's ACP PT documentation found the laboratory's received a score of "Unacceptable" on the follow PT samples: 2019 - 3rd Testing Event MLE-M3 Testosterone SC-5 SC-6 No documentation of corrective actions for the "Unacceptable" sample were present. 2020 -1st Testing Event MLE-M1 Testosterone SC-1 No documentation of corrective actions for the "Unacceptable" sample were present 2020 -2nd Testing Event MLE-M2 Testosterone SC-3 SC-4 No documentation of corrective actions for the "Unacceptable" sample were present On the date of survey, TP#2 was unable to locate corrective action documentation for the "Unacceptable" samples. 2. TP#2 confirmed no documentation of corrective actions were present or were able to located for the "Unacceptable" samples noted above. The interview occurred 08/26/2020 at 14:15 PM.</p>