

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 18D1092600	(X3) Date Survey Completed 11/07/2022
Name of Provider or Supplier Advanced Biomedical Db a United Diagnostic Lab	Street Address, City, State 2754 Veach Road, Owensboro, KY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A recertification survey and an abbreviated survey investigating complaint KY37964 were conducted on 11/07/2022. There were no deficiencies related to the complaint. The facility failed to meet the requirements below during the recertification survey, with deficiencies cited.
D5407	<p>PROCEDURE MANUAL CFR(s): 493.1251(d)</p> <p>Procedures and changes in procedures must be approved, signed, and dated by the current laboratory director before use.</p> <p>This STANDARD is not met as evidenced by: Based on interview and review of the facility's policies and procedures, the laboratory failed to ensure the updated laboratory procedure manual was signed and dated by the laboratory director. The findings include: Review of the laboratory's policies and procedure manual revealed that the manual was updated on 01/01/2022; however, the laboratory director had not signed or dated the updated manual. Interview with the Owner, on 11/07/2022 at 3:10 PM, revealed that the laboratory director visited the facility quarterly to perform reviews and had not yet visited for the current quarter. Further interview revealed the the updated procedure manual was dated 01/01/2022 prior to the current quarter, and still had not been signed or dated by the laboratory director.</p>