

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 18D2272280	(X3) Date Survey Completed 06/05/2026
Name of Provider or Supplier Baptist Health Louisville At Blankenbaker	Street Address, City, State 11701 Bluegrass Pkwy Suite 100, Louisville, KY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A recertification survey was conducted on 06/05/2026 and concluded on 06/05/2026. The facility was found to not be in compliance with the laboratory requirements of 42 CFR Part 493 with standard deficiencies cited.
D6080	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(c)</p> <p>(c) The laboratory director must: (c)(1) Be onsite at least once every 6 months, with at least 4 months between the minimum two on-site visits. Laboratory directors may elect to be on-site more frequently and must continue to be accessible to the laboratory to provide telephone or electronic consultation as needed; and (c)(2) Provide documentation of these visits, including evidence of performing activities that are part of the laboratory director responsibilities.</p> <p>This STANDARD is not met as evidenced by: Based on a review of CMS (Centers for Medicare and Medicaid Services)-209 form and confirmed in staff interview, the Laboratory Director (LD) failed to be onsite for 2 of 2 visits for the year 2025. Findings include: Review of CMS-209 form submitted at time of survey, revealed one active Director. No documentation of Laboratory Director visits were provided for review. During an interview in the conference room at 11:30 AM, the Technical Consultant (TC) stated the acting Laboratory Director (LD) had not performed the minimum two onsite visits for the year of 2025. This confirmed the findings.</p>