

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  20D0089847	<b>(X3) Date Survey Completed</b>  03/07/2024
<b>Name of Provider or Supplier</b>  Northern Light Blue Hill Memorial Hospital	<b>Street Address, City, State</b>  57 Water Street, Blue Hill, ME	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6046</b>	<p><b>TECHNICAL CONSULTANT RESPONSIBILITIES</b> CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on record review and staff interview, the Technical Consultant (TC) failed to evaluate the competency of all Testing Personnel (TP) to perform moderate complexity testing. Findings include: 1. Record review on 3/6/2024 of the laboratory's 2024 TP competency records revealed 6 of 6 moderate complexity TP did not have complete competency performed by the TC. 2. Staff interview with the TC on 3/6 /2024 at 10: PM confirmed the above findings. 3. The laboratory performs approximately 121,632 Moderate Complexity test per year.</p>