

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 21D0211731	(X3) Date Survey Completed 09/24/2019
Name of Provider or Supplier Internal Medicine Of Chevy Chase, Pa	Street Address, City, State 5530 Wisconsin Avenue, Suite 1400, Chevy Chase, MD	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview with the laboratory consultant, the laboratory director acting as the technical consultant failed to perform and document the competency reviews on all testing personnel. Findings: 1. The laboratory currently has 4 testing personnel listed on the "Laboratory Personnel Report (CLIA) (CMS-209)." 2. A review of competency testing records showed that there were no competency assessments performed on 1 of 4 testing personnel performing chemistry and hematology testing in 2018 and 2019. 2. During the survey on 9/24/19 at 4:30 PM the laboratory consultant confirmed that there were no competency evaluations performed on testing person #1 for 2018 and 2019.</p>