

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  21D0212217	<b>(X3) Date Survey Completed</b>  09/13/2021
<b>Name of Provider or Supplier</b>  Shady Grove Pediatric Associates	<b>Street Address, City, State</b>  15215 Shady Grove Road Suite 303, Rockville, MD	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6054</b>	<p><b>TECHNICAL CONSULTANT RESPONSIBILITIES</b> CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on review of the "Laboratory Personnel Report (CLIA) (CMS-209), annual evaluation documentation and interview with the testing person (TP), the technical consultant failed to ensure that all of the TP received an annual evaluation as required. Findings: 1. The CMS-209 lists six TP. One of the TP is the laboratory director. 2. The annual evaluations for 2019 through 2021 were reviewed. The records showed that two of the five TP listed on the CMS-209 did not have an annual evaluation performed during that time period. 3. During the survey on 09/13/2021 at 10:45 AM, the TP confirmed that the records did not include an annual evaluation of two of the five TP listed on the CMS-209.</p>