

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  21D1083426	<b>(X3) Date Survey Completed</b>  07/21/2022
<b>Name of Provider or Supplier</b>  Medstar Med Grp Southern Md Llc/ Cancer Rec Ctr	<b>Street Address, City, State</b>  23415 Three Notch Road Suite 2050, California, MD	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6046</b>	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on competency testing record review and interview with the technical consultant (TC), the TC did not document the competency review on all testing personnel (TP) in the laboratory. Findings: 1. The laboratory currently has 8 testing personnel listed on the "Laboratory Personnel Report (CLIA)" (CMS-209). 2. Each TP has a sheet where the TC records the dates that each TP was "Shown or Demonstrated," "Date Successfully Performed," "6 month review," and "Annual review." 3. A review of competency assessment records from 2020 to 2022 showed that for 4 of 8 TP, competency assessment records were present for the TP's initial training and 6 month competency assessments. There was no competency assessment documentation present at the time of the survey for annual reviews performed on the dates recorded on each TP's sheet. 4. During an interview on 07/21/2022 at 12:15 PM, the TC stated that the competency assessments had been performed, but confirmed that documentation of these assessments was not present at the time of the survey.</p>