

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b> 22D0067542	<b>(X3) Date Survey Completed</b> 02/25/2021
<b>Name of Provider or Supplier</b> Memorial Square Laboratory	<b>Street Address, City, State</b> 2150 Main St, Springfield, MA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	A CLIA recertification survey was conducted for the Memorial Square Laboratory pursuant to the Clinical Laboratory Improvement Amendments (CLIA) of 1988 and CLIA regulations at 42 CFR 493. Refer to Conditions of Participation for Clinical Laboratories 42 CFR Part 493. .
<b>D6054</b>	<p><b>TECHNICAL CONSULTANT RESPONSIBILITIES</b> CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview, the technical consultant failed to evaluate and document the performance of all individuals responsible for moderate complexity testing at least annually as evidenced by the following: a) Findings revealed that the technical consultant failed to evaluate the competency, at least annually, of one (1) out of two (2) laboratory technologists for calendar years 2019 and 2020. b) This was confirmed through an interview with the laboratory technologist on 2/25/21 at 9:29 AM. and the technical consultant on 2/24/21 at 1:15 PM</p>