

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 23D0367948	(X3) Date Survey Completed 11/05/2020
Name of Provider or Supplier Quasar Laboratory	Street Address, City, State 20331 Farmington Road, Livonia, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3007	<p>FACILITIES CFR(s): 493.1101(b)</p> <p>The laboratory must have appropriate and sufficient equipment, instruments, reagents, materials, and supplies for the type and volume of testing it performs.</p> <p>This STANDARD is not met as evidenced by: . Based on observation, record review, and interview with the testing personnel, the laboratory failed to have sufficient equipment for the testing it performs for 2 (November 2018 to November 2020) of 2 years. Findings include: 1. An observation on 11/5/20 at 8:54 am by the surveyor revealed a Sterling Diagnostics IsoComp I. 2. An interview on 11/5/20 at 8:54 am with the testing personnel revealed the printer on the Sterling Diagnostics IsoComp I analyzer was broken. 3. A review of the Sterling Diagnostics IsoComp I analyzer data revealed a lack of instrument printouts to verify transcribed data from November 2018 to November 2020 for the following processes: a. Background counts b. Quality control c. Calibrations d. Patient test results</p>