

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  23D2077425	<b>(X3) Date Survey Completed</b>  02/17/2021
<b>Name of Provider or Supplier</b>  Dermatology Specialists Of Brighton	<b>Street Address, City, State</b>  2305 Genoa Business Park Dr, Suite 180, Brighton, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D3001</b>	<p>FACILITIES CFR(s): 493.1101(a)(1)</p> <p>The laboratory must be constructed, arranged, and maintained to ensure the space, ventilation, and utilities necessary for conducting all phases of the testing process.</p> <p>This STANDARD is not met as evidenced by: . Based on observation, record review, and interview with the Office Manager, the laboratory failed to have ventilation or respiratory protection available while the laboratory when using XS-3 Xylene Substitute for 2 (February 2019 to February 2021) of 2 years reviewed. Findings include: 1. An observation made on 2/17/21 at 9:10 am during the tour of the laboratory revealed the laboratory was small, did not have a ventilation hood, and it was using XS-3 Xylene Substitute. 2. A review of the laboratory's Safety Data Sheet for the XS-3 Xylene Substitute revealed a section stating, "Personal Protective Equipment: Gloves. Protective clothing. Protective goggles. Insufficient ventilation: wear respiratory protection." 3. An interview on 2/17/21 at 10:22 am with the Office Manager revealed the laboratory does not have a ventilation system, ventilation hood, or respiratory protection for the appropriate staff for the use of XS-3 Xylene Substitute.</p>