

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 23D2077428	(X3) Date Survey Completed 02/17/2021
Name of Provider or Supplier Dermatology Specialists Of Canton	Street Address, City, State 361 N Canton Center Rd, Canton, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3001	<p>FACILITIES CFR(s): 493.1101(a)(1)</p> <p>The laboratory must be constructed, arranged, and maintained to ensure the space, ventilation, and utilities necessary for conducting all phases of the testing process.</p> <p>This STANDARD is not met as evidenced by: . Based on observation, record review, and interview with the Office Manager, the laboratory failed to have ventilation or respiratory protection available while the laboratory when using XS-3 Xylene Substitute for 2 (February 2019 to February 2021) of 2 years reviewed. Findings include: 1. An observation made on 2/17/21 at 9:10 am during the tour of the laboratory revealed the laboratory was small, did not have a ventilation hood, and it was using XS-3 Xylene Substitute. 2. A review of the laboratory's Safety Data Sheet for the XS-3 Xylene Substitute revealed a section stating, "Personal Protective Equipment: Gloves. Protective clothing. Protective goggles. Insufficient ventilation: wear respiratory protection." 3. An interview on 2/17/21 at 12:35 pm with the Office Manager revealed the laboratory does not have a ventilation system, ventilation hood, or respiratory protection for the appropriate staff for the use of XS-3 Xylene Substitute.</p>