

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 23D2209126	(X3) Date Survey Completed 06/03/2026
Name of Provider or Supplier Bellin Health Escanaba	Street Address, City, State 610 S Lincoln Road, Escanaba, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	. A proficiency testing desk review survey was performed on June 3, 2026, by the State of Michigan Department of Licensing and Regulatory Affairs. The laboratory was found to be out of compliance with CLIA regulations (42 CFR Part 493, Laboratory Requirements) for the following Conditions: 493.803 Condition: Successful participation.
D2016	SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c) (a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history. This CONDITION is not met as evidenced by: . Based on review of the CMS database, Wisconsin State Laboratory of Hygiene

	(WSLH) proficiency testing reports and interview with the laboratory manager, the laboratory failed to achieve satisfactory performance for the chemistry analytes Blood Urea Nitrogen (BUN) and Uric Acid. Refer to D2096.
D2096	ROUTINE CHEMISTRY CFR(s): 493.841(f) (f) Failure to achieve satisfactory performance for the same analyte or test in two consecutive testing events or two out of three consecutive testing events is unsuccessful performance. This STANDARD is not met as evidenced by: . Based on review of the CMS database, Wisconsin State Laboratory of Hygiene (WSLH) proficiency testing reports, and interview with the laboratory manager (LM), the laboratory failed to achieve satisfactory performance for 2 (3rd Event 2025 and 1st Event 2026) of 3 testing events for the specialty Chemistry for the analytes Blood Urea Nitrogen (BUN) and Uric Acid. Findings include: 1. A review of the CMS database and Wisconsin State Laboratory of Hygiene (WSLH) proficiency testing reports revealed the laboratory obtained the following proficiency testing scores for BUN and Uric Acid: PT Event BUN Score Uric Acid Score 3rd Event 2025 60% 60% 1st Event 2026 0% 0% 2. A phone interview on 06/10/2026 at 11:30 am with the laboratory manager confirmed the scores listed above.