

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 23D2209166	(X3) Date Survey Completed 10/01/2025
Name of Provider or Supplier Taylor Diagnostics Imaging	Street Address, City, State 28300 Franklin Road Suite 100, Southfield, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	<p>. A proficiency testing desk review survey was performed on Wednesday, October 1, 2025, by the State of Michigan Department of Licensing and Regulatory Affairs. The laboratory was found out of compliance with CLIA regulations (42 CFR Part 493, Laboratory Requirements) for the following Condition(s): 493.803 Condition: Successful participation.</p>
D2016	<p>SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c)</p> <p>(a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history.</p> <p>This CONDITION is not met as evidenced by: . Based on record review and interview with testing personnel, the laboratory failed to achieve satisfactory performance in the virology proficiency testing program. Refer to D2064.</p>

D2064

VIROLOGY

CFR(s): 493.831(e)

(e) Failure to achieve an overall testing event score of satisfactory performance for two consecutive testing events or two out of three consecutive testing events is unsuccessful performance.

This STANDARD is not met as evidenced by:

Based on record review and interview with testing personnel (TP), the laboratory failed to achieve satisfactory performance in virology for two (2025 events 1 & 2) of three testing events. Findings include: 1. A review of the CMS database and the American Proficiency Institute proficiency testing reports revealed the following scores for virology: a. 2025 event 1 had a score of 40% b. 2025 event 2 had a score of 60%. 2. A phone interview with TP on 10/01/2025 at 12:45 pm confirmed the laboratory's unsuccessful performance for proficiency testing in virology.