

|  |  |   |
|--|--|---|
| <b>Statement of Deficiencies</b>   | <b>(X1) Provider/Supplier/CLIA Identification Number</b><br><br>23D2245698     | <b>(X3) Date Survey Completed</b><br><br>03/16/2022 |
| <b>Name of Provider or Supplier</b><br><br>Garland A F C   | <b>Street Address, City, State</b><br><br>7160 Phaner Highway, Potterville, MI |   |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. |  |   |

| <b>(X4) ID Prefix Tag</b> | <b>Summary Statement of Deficiencies</b>  |
|---------------------------|---|
| <b>D1002</b>              | <p><b>REPORTING OF SARS-CoV-2 TEST RESULTS</b></p> <p>During the Public Health Emergency, as defined in 400.200 of this chapter, each laboratory that performs a test that is intended to detect SARS-CoV-2 or to diagnose a possible case of COVID-19 (hereinafter referred to as a "SARS-CoV-2 test") must report SARS-CoV-2 test results to the Secretary in such form and manner, and at such timing and frequency, as the Secretary may prescribe.</p> <p>This CONDITION is not met as evidenced by:<br/>                     . Based on record review and interview with the manager, the laboratory failed to report all SARS-CoV-2 test results as required for 12 of 12 patients tested since the laboratory started testing patients for SARS-CoV-2 on 9/11/21. Findings include: 1. The surveyor requested documentation of the laboratory's attempts to report all SARS-CoV-2 testing results using its Abbott BinaxNOW SARS-CoV-2 antigen testing system on 3/10/22 at 1:35 pm and it was not made available. 2. A phone interview on 3/10/22 at 9:55 am with the manager revealed the laboratory had not reported SARS-CoV-2 patient test results to the health department as required. 3. Email correspondence from the manager on 3/16/22 indicated the laboratory started testing on 9/11/21 and tested 12 patients to date.</p> |