

| | | |
|--|---|---|
| Statement of Deficiencies | (X1) Provider/Supplier/CLIA Identification Number 24D0401213 | (X3) Date Survey Completed 12/05/2019 |
| Name of Provider or Supplier Pediatric Services, Pa | Street Address, City, State 4700 Park Glen Road, Saint Louis Park, MN | |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. | | |

| (X4) ID Prefix Tag | Summary Statement of Deficiencies |
|---------------------------|---|
| D6046 | <p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: . Based on document review and interview with laboratory personnel, the technical consultant (TC) failed to evaluate testing personnel for competency in Microbiology (Bacteriology) moderately complex test procedures performed by the laboratory. Findings are as follows: 1. The laboratory performed Microbiology (Bacteriology) testing as confirmed by the Clinic Manager (CM) during a tour of the laboratory on 12/05/19 at 9:05 a.m. 2. The CM stated the laboratory testing personnel set-up throat and urine cultures and clinic physicians determined the test results. 3. Competency assessments for determining culture test results were not present in 2018 laboratory records for 6 of 6 physicians responsible for this task. 4. The laboratory was unable to provide the competency assessments upon request. 5. In an interview on 12/05/19 at 10:30 a.m., the CM confirmed the above findings. NOTE: this is a repeat deficiency from the 12/08/17 survey. .</p> |