

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  24D2065288	<b>(X3) Date Survey Completed</b>  03/28/2018
<b>Name of Provider or Supplier</b>  Premier Biotech Labs, Llc	<b>Street Address, City, State</b>  723 Kasota Ave Se, Minneapolis, MN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6120</b>	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: . Based on document review and interview with laboratory personnel, the technical supervisor failed to evaluate 5 of 5 testing personnel for Toxicology test procedure competency in 2017. Findings are as follows: 1. The laboratory performed Toxicology testing as confirmed by the Technical Supervisor (TS) during a tour of the laboratory on 03/28/18 at 9:05 a.m. 2. Review of competency assessment documents did not indicate the Technical Supervisor or Testing Personnel 1, 2, 3, or 5 (TP1,TP2, TP3, TP5 ) were evaluated for Toxicology test procedures competency in 2017. 3. The laboratory was unable to provide documentation of these competency evaluations upon request. 4. In an interview on 03/28/18 at 10:45 a.m., the TS confirmed the above findings. .</p>