

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 26D0443515	(X3) Date Survey Completed 12/15/2021
Name of Provider or Supplier Planned Parenthood Great Plains	Street Address, City, State 711 N Providence Rd, Columbia, MO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on review of competency/performance evaluations and interview with the program manager , the technical consultant failed to evaluate and document the competency for one of one testing personnel performing moderate complexity testing for 2020. Findings: 1. Review of competency/performance evaluations revealed no documentation to show the technical consultant evaluated and documented the competency for one testing personnel performing moderate complexity testing of KOHs. 2. Interview with Program Manager on December 15, 2021 at 10:00 AM confirmed the technical consultant failed to evaluate and document the competency of all testing personnel for 2020.</p>