

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  26D0445875	<b>(X3) Date Survey Completed</b>  12/14/2021
<b>Name of Provider or Supplier</b>  Lake Regional Health System - Laurie Clinic	<b>Street Address, City, State</b>  156 Missouri Blvd Ste B, Laurie, MO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6036</b>	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413</p> <p>The technical consultant is responsible for the technical and scientific oversight of the laboratory.</p> <p>This STANDARD is not met as evidenced by: Based on review of quality control (QC) records and interview with the laboratory director (LD), the technical consultant (TC) failed to provide technical and scientific oversight of the laboratory. Findings: 1. Review of complete blood count (CBC) QC showed no documentation of TC review since July 2021. 2. Interview with the LD on December 14, 2021 at 11:00 AM confirmed the TC failed to provide technical and scientific oversight of CBC testing.</p>