

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  26D0710684	<b>(X3) Date Survey Completed</b>  03/12/2018
<b>Name of Provider or Supplier</b>  Freeman Urology Associates	<b>Street Address, City, State</b>  3302 McIntosh Circle, Ste 2, Joplin, MO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D2003</b>	<p>ENROLLMENT CFR(s): 493.801(a)(2)(ii)</p> <p>For those tests performed by the laboratory that are not included in subpart I of this part, a laboratory must establish and maintain the accuracy of its testing procedures, in accordance with 493.1236(c)(1)</p> <p>This STANDARD is not met as evidenced by: Based on review of post vasectomy sperm count test accuracy and interview with testing personnel #1 the laboratory failed to perform test accuracy for one of two testing events in 2016. Findings: 1. Review of "post vas sperm count lab competency log" showed the laboratory did not perform test accuracy two times in 2016. 2. Interview with testing personnel #1 on March 12, 2017 at 10:00 AM confirmed the laboratory failed to perform test accuracy two times in 2016 for "post vas sperm count."</p>