

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 26D0975540	(X3) Date Survey Completed 08/04/2022
Name of Provider or Supplier University Health Lakewood Respiratory	Street Address, City, State 2301 Holmes Street, Kansas City, MO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6054	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on annual performance evaluations and interview with the technical consultant (TC), the TC failed to document annual performance evaluations for 2 of 15 testing personnel in 2020. Findings: 1. Review of performance evaluations in 2020 showed no annual performance evaluation documented for TP #7 and TP #12. 2. Interview with the TC on August 4, 2022 at 12:30 PM confirmed the TC failed to document annual performance evaluations for 2 TP in 2020.</p>