

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  26D0985655	<b>(X3) Date Survey Completed</b>  08/25/2021
<b>Name of Provider or Supplier</b>  Boyce & Bynum Professional Services	<b>Street Address, City, State</b>  1241 W Stadium Blvd, Jefferson City, MO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5413</b>	<p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(b)</p> <p>The laboratory must define criteria for those conditions that are essential for proper storage of reagents and specimens, accurate and reliable test system operation, and test result reporting. The criteria must be consistent with the manufacturer's instructions, if provided. These conditions must be monitored and documented and, if applicable, include the following: (1) Water quality. (2) Temperature. (3) Humidity. (4) Protection of equipment and instruments from fluctuations and interruptions in electrical current that adversely affect patient test results and test reports.</p> <p>This STANDARD is not met as evidenced by: Based on review of temperature logs, and interview with the laboratory director (LD), the laboratory failed to document the cryostat temperature from October 2020 to date August 25, 2021. Findings: 1. Review of temperature logs showed no documentation of cryostat temperature from October 2020 to date August 25, 2021. 2. Interview with LD on August 25, 2021 at 11:30 AM confirmed the laboratory failed to document the cryostat temperature.</p>