

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 27D0409929	(X3) Date Survey Completed 08/26/2021
Name of Provider or Supplier Prairie Community Hospital	Street Address, City, State 312 South Adams, Terry, MT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5439	<p>CALIBRATION AND CALIBRATION VERIFICATION CFR(s): 493.1255(b)</p> <p>Unless otherwise specified in this subpart, for each applicable test system the laboratory must do the following: Perform and document calibration verification procedure - (b)(1) Following the manufacturer's calibration verification instructions; (b)(2) Using the criteria verified or established by the laboratory under 493.1253(b)(3) -- (b)(2)(i) Including the number, type, and concentration of the materials, as well as acceptable limits for calibration verification; and (b)(2)(ii) Including at least a minimal (or zero) value, a mid-point value, and a maximum value near the upper limit of the range to verify the laboratory's reportable range of test results for the test system; and (b)(3) At least once every 6 months and whenever any of the following occur: (b)(3)(i) A complete change of reagents for a procedure is introduced, unless the laboratory can demonstrate that changing reagent lot numbers does not affect the range used to report patient test results, and control values are not adversely affected by reagent lot number changes. (b)(3)(ii) There is major preventive maintenance or replacement of critical parts that may influence test performance. (b)(3)(iii) Control materials reflect an unusual trend or shift, or are outside of the laboratory's acceptable limits, and other means of assessing and correcting unacceptable control values fail to identify and correct the problem. (b)(3)(iv) The laboratory's established schedule for verifying the reportable range for patient test results requires more frequent calibration verification.</p> <p>This STANDARD is not met as evidenced by: Based on review of the calibration records for the Sysmex XP-300 hematology analyzer for complete blood counts (CBC) with differential, and interview with the laboratory director (LD) #1, the laboratory failed to perform the manufacturer's recommended calibration in year 2019. Findings: 1. No calibration records for the</p>

Sysmex XP-300 hematology analyzer for 2019 were available for review. 2. Interview with the LD #1 on August 26, 2021 at 11:00 AM confirmed the laboratory failed to perform the manufacturer's recommended calibration for year 2019.