

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 27D0678565	(X3) Date Survey Completed 09/09/2020
Name of Provider or Supplier Mountainview Medical Center	Street Address, City, State 16 West Main St, White Sulphur Springs, MT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6127	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9)</p> <p>The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least semiannually during the first year the individual tests patient specimens.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview, the laboratory failed to perform competency assessment twice during the first year for one of one new testing personnel (TP#1). Findings: 1. Review of personnel competency evaluations revealed that TP#1 only had one competency assessment performed during the first year of patient testing. 2. Review of Mountainview Medical Center's IQPC plan revealed competency was to be performed twice during the first year. 3. Confirmed during interview on 9/9/2020 at 10:10am with Technical Supervisor, the laboratory failed to perform twice annual competency assessment for TP#1.</p>