

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 28D0456013	(X3) Date Survey Completed 10/13/2020
Name of Provider or Supplier Valley County Health System - Laboratory	Street Address, City, State 2707 L Street, Ord, NE	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6055	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing whenever test methodology or instrumentation changes. The individual's performance must be reevaluated to include the use of the new test methodology or instrumentation prior to reporting patient test results.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of new instrumentation and personnel records, and technical consultant interview, the laboratory failed to document testing personnel training of four of four testing personnel prior to use of new moderate complexity instrument. The findings include: 1. Review of new instrumentation revealed a new moderate complexity beta-hydroxybutyrate instrument was put in service on September 2018. 2. No documentation of training was found in the personnel records for the new moderate complexity beta-hydroxybutyrate instrument prior to reporting patient test results. 3. Interview with the technical consultant on 10/13/2020 confirmed no documentation of training available at time of survey.</p>