

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 30D2044558	(X3) Date Survey Completed 12/14/2020
Name of Provider or Supplier Mystic Valley Dermatology Associates	Street Address, City, State 29 Stiles Rd, Ste 303, Salem, NH	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6084	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(2)</p> <p>The laboratory director must ensure that the physical plant and environmental conditions provide a safe environment in which employees are protected from physical, chemical, and biological hazards.</p> <p>This STANDARD is not met as evidenced by: Based on observation and staff interview, the laboratory director failed to ensure suitable flooring located in the laboratory that can be disinfected in the event of biohazardous contamination. Findings include: 1) Observation of the laboratory on 12/14/2020 at 9:45 a.m. revealed carpeted flooring in the areas where tissue samples are inked and mapped, slide preparation (tissue cutting and staining procedures) is performed, and storage of hazardous chemicals occurs. 2) Interview with the Clinical Program Services Administration confirmed the above finding. 3) The laboratory could not demonstrate how it would disinfect the carpeted flooring in the event of a biohazardous material contacts the floor.</p>