

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 31D1092394	(X3) Date Survey Completed 08/15/2018
Name of Provider or Supplier Electron Microscopy Laboratory	Street Address, City, State 683 Hoes Lane West, Piscataway, NJ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6102	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(12)</p> <p>The laboratory director must ensure that prior to testing patients' specimens, all personnel have the appropriate education and experience, receive the appropriate training for the type and complexity of the services offered, and have demonstrated that they can perform all testing operations reliably to provide and report accurate results.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of the Personnel Files (PF) and interview with the Laboratory Director (LD), the LD failed to have foreign education equivalency for one out of one testing personnel from 8/8/16 to the date of survey. The LD confirmed on 8/15/18 at 1:50 pm that foreign education evaluation was not in the PF.</p>