

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 31D2025770	(X3) Date Survey Completed 12/21/2018
Name of Provider or Supplier Kessel Dermatology	Street Address, City, State 1700 Whitehorse Hamilton Sq Road, Hamilton Square, NJ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6103	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(13)</p> <p>The laboratory director must ensure that policies and procedures are established for monitoring individuals who conduct preanalytical, analytical, and postanalytical phases of testing to assure that they are competent and maintain their competency to process specimens, perform test procedures and report test results promptly and proficiently, and whenever necessary, identify needs for remedial training or continuing education to improve skills.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of the Procedure Manual (PM) and interview with the Testing Personnel (TP), the Laboratory Director failed to establish a Competency Assessment (CA) procedure with the applicable elements for Mohs technician on the date of survey. The TP # 1 listed on CMS form 209 confirmed on 12/21/18 at 10:30 am that a CA procedure was not established.</p>