

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  31D2074207	<b>(X3) Date Survey Completed</b>  11/15/2022
<b>Name of Provider or Supplier</b>  New Jersey Interventional	<b>Street Address, City, State</b>  3 Cornwall Drive, East Brunswick, NJ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6088</b>	<p><b>LABORATORY DIRECTOR RESPONSIBILITIES</b> CFR(s): 493.1445(e)(4)</p> <p>The laboratory director must ensure that the laboratory is enrolled in an HHS-approved proficiency testing program for the testing performed.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of the Proficiency Testing (PT) records and interview with the General Supervisor (GS), the Laboratory Director (LD) failed to ensure that PT samples were tested for all analytes run on the AB Sciex analyzers from 12/30/19 to the date of the survey. The findings include: 1. Not all analytes run on the AB Sciex analyzer are offered for PT testing in each College of American Pathologists (CAP) survey events. 2. The GS confirmed on 11/15/22 at 11:35 am that the LD did not ensure PT samples were tested for all tests performed in the laboratory.</p>