

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 31D2122628	(X3) Date Survey Completed 07/27/2021
Name of Provider or Supplier Reproductive Medicine Associates	Street Address, City, State 955 South Springfield Ave, Springfield, NJ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5209	<p>PERSONNEL COMPETENCY ASSESSMENT POLICIES CFR(s): 493.1235</p> <p>As specified in the personnel requirements in subpart M, the laboratory must establish and follow written policies and procedures to assess employee and, if applicable, consultant competency.</p> <p>This STANDARD is not met as evidenced by: Based on the lack of Competency Assessment (CA) records and interview with the Laboratory Manager (LM), the laboratory failed to follow written procedures to perform a CA on eleven of eleven Testing Personnel for the calendar years 2019 and 2020. The LM confirmed on 7/27/21 at 11:30 am that the CA procedure was not followed .</p>
D5215	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(b)(2)</p> <p>The laboratory must verify the accuracy of any analyte, specialty or subspecialty assigned a proficiency testing score that does not reflect laboratory test performance (that is, when the proficiency testing program does not obtain the agreement required for scoring as specified in subpart I of this part, or the laboratory receives a zero score for nonparticipation, or late return or results).</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of the Proficiency Testing (PT) records and interview with the Laboratory Manager (LM), the laboratory failed to verify the accuracy of Andrology test results obtained from the American Association of Bioanalysts (AAB) from May 2020 to the date of survey. The findings include: 1. The laboratory received a 100 but results were not graded. 2. There was no documented evidence the</p>

	<p>laboratory verified: a) Sperm count in Andrology & Embryology event S1 2020. b) Sperm Motility in Andrology & Embryology events S2 2020 and S1 2021. 2. The LM confirmed on 7/27/21 at 12:10 pm accuracy of the PT results were not verified</p>
<p>D6091</p>	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(4)(iii)</p> <p>The laboratory director must ensure all proficiency testing reports received are reviewed by the appropriate staff to evaluate the laboratory's performance and to identify any problems that require corrective action.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of the Proficiency Testing (PT) records and interview with the Laboratory Manager (LM), the Laboratory Director (LD) failed to ensure that Andrology results performed with the American Association of Bioanalysts (AAB) were reviewed and evaluated by the appropriate staff. The findings include: 1. There was no documented evidence the laboratory reviewed: a) Sperm count in Andrology & Embryology event S1 2020. b) Sperm Motility in Andrology & Embryology events S2 2020 and S1 2021. 2. The LM confirmed on 7/27/21 at 10:50 am that the LD did not ensure all PT reports were reviewed.</p>
<p>D6102</p>	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(12)</p> <p>The laboratory director must ensure that prior to testing patients' specimens, all personnel have the appropriate education and experience, receive the appropriate training for the type and complexity of the services offered, and have demonstrated that they can perform all testing operations reliably to provide and report accurate results.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of Personnel Records (PR) and interview with the Laboratory Manager (LM), the Laboratory Director failed to ensure that the education records were available on the date of the survey. The finding includes: 1. Education records were not available for six of eleven Testing Personnel (TP). 2. The LM confirmed on 7/27/2021 at 10:00 am that education records were not available.</p>