

|  |  |   |
|--|--|---|
| <b>Statement of Deficiencies</b>   | <b>(X1) Provider/Supplier/CLIA Identification Number</b><br><br>31D2221005 | <b>(X3) Date Survey Completed</b><br><br>04/29/2025 |
| <b>Name of Provider or Supplier</b><br><br>Thplasma Elizabeth  | <b>Street Address, City, State</b><br><br>81 Broad Street, Elizabeth, NJ   |   |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. |  |   |

| <b>(X4) ID Prefix Tag</b> | <b>Summary Statement of Deficiencies</b>  |
|---------------------------|---|
| <b>D6074</b>              | <p>TESTING PERSONNEL RESPONSIBILITIES<br/>CFR(s): 493.1425(b)(5)</p> <p>(b)(5) Be capable of identifying problems that may adversely affect test performance or reporting of test results and either must correct the problems or immediately notify the technical consultant, clinical consultant or director; and</p> <p>This STANDARD is not met as evidenced by:<br/>Based on surveyor review of the Quality Control (QC) records and interview with the Corporate Quality Manager (CQM), the Testing Personnel failed to identify problems that may affect test performance by not reviewing and evaluating trends and/or shifts of Routine Chemistry QC results performed on the REICHERT Digital Refractometer analyzers from June 2021 to 4/29/25. The CQM confirmed on 4/29/25 at 11:10 am that trends and shifts were not reviewed. Note: This deficiency was previously cited.</p> |